

Date: Friday, 9/21/2007 1:18:27 PM  
 User: Kim Johnston

## Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : BUSHING
Job Number : 34811	
Estimate Number : 10175	
P.O. Number : <i>N/A</i>	Part Number : D2570
This Issue : 9/21/2007 S.O. No. : <i>N/A</i>	Drawing Number : D2570 REV B
Prsht Rev. : NC	Project Number : <i>N/A</i>
First Issue : 9/21/2007 Type : MACHINED PARTS	Drawing Revision : B
Previous Run : 33559	Material : <i>N/A</i>
Written By : <i>[Signature]</i>	Due Date : 10/20/2007
Checked & Approved By : <i>[Signature]</i>	Qty: <i>505</i> Um: Each
Comment : Est E 02.08.29 Re-format; Removed finishing; Material changeK J est F 07.07.06 rev B dwg EC	

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	M303R0750	303 Round Bar .75"
-----	-----------	--------------------



Comment: Qty.: 0.0810 f(s)/Unit Total : 40.4775 f(s)

Material: Ø0.750 AISI 303 SS Rod (M303R0.750)

Batch *M104973-x60 DIP 07/10/01 IP 07/10/02-03* *37.3"*

2.0	HARDINGE	HARDINGE CNC LATHE SMALL
-----	----------	--------------------------



Comment: HARDINGE CNC LATHE SMALL

Machine as per folio FA198

Deburr and tumble

*DIP 07/10/01 IP 07/10/02-03*

3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

*DIP 07/10/01 IP 07/10/02-03* *(505)*

4.0	QC8	SECOND CHECK
-----	-----	--------------



Comment: SECOND CHECK

*J.L 07/10/03*

5.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: \_\_\_\_\_

*[Signature] 07/10/03 (505)*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes ☒ No ☐ DQA: LD Date: 07/10/04  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			
			I					

NOTE: Date & initial all entries

Date: Friday, 9/21/2007 1:18:27 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BUSHING

Job Number: 34811

Part Number: D2570

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



(SCS)

Comment: FINAL INSPECTION/W/O RELEASE

12/18/04

Job Completion



U 07-1004

**Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries



**DART**

DESIGN PH	DRAWN BY PH	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED H	APPROVED H	DRAWING NO. D2570	REV. B SHEET 1 OF 1
DATE 07.04.17		TITLE BUSHING	SCALE 1:1
A	96.09.16	NEW ISSUE	
B	07.04.17	UPDATE NOTES	

**RELEASED**  
07.06.28 H**D2570 BUSHING****D2570 BUSHING**

- 1) MATERIAL: AISI 303 ROUND BAR (REF. DART SPEC. M303R)
- 2) FINISH: NONE
- 3) ALL DIMENSIONS ARE INCHES
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) BREAK ALL UNMARKED SHARP EDGES TO 0.010 MAX

SH 10 Y  
RE 10 C  
ENC 10  
UNCONTROLLED COPY  
SUBJECT TO  
WITH  
NO. 34811

**Copyright © 1996 by DART AEROSPACE LTD**

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.